



*One of several extremely sentimental music stands needing structural and finish repair, and to be cleaned thoroughly.*





*MPFC repaired the break in the hinged music stand and in the cross bracing.*





*We cleaned and protected the base.*





*Care was taken with the finish to clean then protect the existing finish, which had several areas where a family member's music had been stuck in the finish. The Finish had, in order: cleaning, a barrier coat, a top coat of shellac, and then a protective wax coat.*

